

# INSPECTION INFORMATION

EXCAVATOR

<b>SH240-5-SL2922</b>		YEAR	2012YR
		HOUR	26948Hrs
SPEC	W/5 PIPES, 2WAY LEVER,ELEVATOR CAB, W/AIR-CON, MATERIAL HANDLING FRONT, FORK ONLY, ERROR CODE ON DISPLAY "ELECTRICAL SYSTEM"		Confirmed
		SHOE	FLAT SHOE
PLATE NO.	SMT240A5H00SL2922	STAMP	SMT240A5H00SL2922

ENGINE	Maker	ISUZU	Model	4HK1	
	S/No.	490719	EXHAUST GAS REGULATIONS	TIER 3	3次

CONDITION				
	GOOD	FAIR	NOTE	特記
ENGINE			<b>BLOW BY</b>	排圧
MAIN PUMP		○		
SWING BEARING		○		
TRAVEL MOTOR		○		
APPEARANCE			<b>OPERATING LEVER COVER= BROKEN (SEE PHOTO) SIDE COVER= BEND</b>	操作レバーカバー破損 (写真参照) 側面カバー曲り
UNDER CARRIAGE			<b>SHOE PLATE= BROKEN</b>	シュープレート割れ
BOOM		○		
ARM		○		
HYD. CYLINDER		○		
BATTERY				
COMMENTS				

**TOZAI BOEKI CO., LTD.**

This inspection information is for reference only. It is not to guarantee the condition of the actual machine.  
この査定情報はあくまで参考資料であり、実際の機械の状態を保証するものではありません。